

HIKE A HUSBAND

QUOTE FOR PARTS AND LABOUR

16th December 2025

K6 Telephone Box, Limpsfield.

Remove and dispose of all 72 panes of glass and frames.

Remove internal boards and metal box below.

Clear soil behind and around the box to ground level.

Trim the door frame to allow closing.

Scrape loose/flaking paint, wire brush, sand and wash down internally and externally ready for painting.

Prime bare areas with red oxide metal primer and paint with two coats of BS 539 Current Red gloss paint.

Paint the high level external crowns in gold.

Fit 72 panes of toughened glass, push/pull sign and steel frames.

Fit new 18mm plywood back-board.

Fit four shelves on brackets to the back of the box and paint in a colour to be confirmed.

Materials:

Toughened glass set inc. Push/Pull sign	£377.19
Steel glazing frame set	£1050.91
1 litre Red oxide primer	£29.02
3 litres BS 539 Current Red gloss paint	£93.49
1 sheet 18mm x 2440 x 1220 ply	£45.00
250ml Ronseal exterior gold paint	£13.00
8 x shelf brackets	£40.00
Tapered glazing pin set	£35.23
Materials Total inc. VAT	£1673.84

Labour (no VAT)	£2800.00
TOTAL	£4473.84
Contingency at 20%	£894.60
TOTAL inc Vat	£5368.44

NOTE FROM ANDREW

This quote does not include parts or labour to repair the broken glazing bar in the door.

I have not yet been able to speak to Unicorn Restorations about the cost of replacing this part.

When I speak to them I will also ask about the practicality and cost of sandblasting the whole phone box in situ.

I will let you know when I have spoken to them.

My quote includes collection of the materials from Unicorn Restorations in Merstham.

Yours sincerely
Andrew Jackson